

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number K 50007246846		2. Page 1 of 1		3. Emergency Response Phone (800) 483-3711		4. Manifest Tracking Number 008037398 FLE				
		5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219						Generator's Site Address (if different than mailing address) SAME				
6. Transporter 1 Company Name Basin		U.S. EPA ID Number OKR000023085										
7. Transporter 2 Company Name		U.S. EPA ID Number										
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40356 S County Road 230 Wamego, OK 73860		U.S. EPA ID Number OKD065488375										
Facility's Phone: (580) 697-3500												
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
						No.	Type					
		1. HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III				1	DT	EST 16	Y	F001	F002	F003
		2.								F004	F005	
		3.										
	4.											
14. Special Handling Instructions and Additional Information 1. CH891502X05 CR38171 TR# 179 TL# 6024												
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.												
Generator's/Offoror's Printed/Typed Name Jim Tyson Signature Jim Tyson Month 2 Day 12 Year 15												
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:											
	Transporter signature (for exports only):											
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials											
	Transporter 1 Printed/Typed Name James Thurber Signature James Thurber Month 2 Day 12 Year 15											
Transporter 2 Printed/Typed Name Signature Month Day Year												
DESIGNATED FACILITY	18. Discrepancy											
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection											
	Manifest Reference Number:											
	18b. Alternate Facility (or Generator) U.S. EPA ID Number											
	Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Month Day Year											
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)												
1. H132		2.		3.		4.						
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a												
Printed/Typed Name Signature Month Day Year												

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846		2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718		4. Manifest Tracking Number 008037398 FLE		
		5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219		Generator's Site Address (if different than mailing address) SAME					
6. Transporter 1 Company Name Basin		U.S. EPA ID Number OKR000023085							
7. Transporter 2 Company Name		U.S. EPA ID Number							
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40355 S County Road 236 Wannoka, OK 73860		U.S. EPA ID Number OKD065438976							
Facility's Phone: (800) 697-3500									
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
		1. HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III			1 DT		EST 16	Y	F001 F002 F003 F004 F005
		2.							
		3.							
		4.							
14. Special Handling Instructions and Additional Information 12CR031502X08 EPO#171 TR# 179 TL# EN24									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offor's Printed/Typed Name Jim Tyson									
Signature Jim Tyson									
Month Day Year 12 12 15									
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:								
	17. Transporter Acknowledgment of Receipt of Materials								
	Transporter 1 Printed/Typed Name Jerred Thurber								
Signature Jerred Thurber									
Month Day Year 12 12 15									
Transporter 2 Printed/Typed Name									
Signature									
Month Day Year									
DESIGNATED FACILITY	18. Discrepancy								
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
	18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number								
	Facility's Phone:								
	18c. Signature of Alternate Facility (or Generator) Month Day Year								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. H132 2. 3. 4.									
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in item 18a									
Printed/Typed Name Handy Hart									
Signature Handy Hart									
Month Day Year 12 12 15									